

SULLY RJLED2 FIRMWARE HISTORY

After updating, refresh your web page and check that you have the following text at the bottom of the page:

ROBERT JULIAT - RJ LED 2 - Version 2.0

It is highly recommended to do a Factory Reset after the update. This can be done from the Web Page or RDM. It should also be noted that user settings will be lost.

V2.2 27/04/21

Corrections/Improvements:

RDM:

- Modification SLOT_INFO PID to be compatible with Zero88 consoles

Web Page:

- Fixed error when uploading firmware with Web Page in DHCP (reload a page with 0.0.0.0)

V2.107 12/04/2021

New Features:

Web Page:

- Added check user function for description change via web page

V2.106 06/04/2021

Corrections/Improvements:

RDM:

- Redesign of RDM code (Get/Set) for optimization
- Added in Queued_Message the management of the parameters modifications (used by ETC) allowing to update the PID if a modification is made via the web page or the display.
- Modification in the autotest (exit from driver test mode)

Error Management:

- Improved error handling (if DAC driver has a fault the system is shut down immediately)

V2.10 23/03/2021

New Features:

Web Page:

- Visual redesign with RJ chart and dark background
- Addition of feedback in SSI
- Added features and password for access to expert menu "1280".
- Creation of a structure called dataWEB to manage the modifications in long processing
- Automatic reconnection to the page after modification on the same network or after a restart

Watchdog :

- Task: restart the network task in case of problems (loss in while 1 or web page loading too long)
- PHY: restart the phy and the network task in case of random reset (electromagnetic discharge ESD)
- Modification of the watchdogs reinitialization delays following ESD tests and web page tests (ESD wd_data_ETH minimum delay after laboratory tests : 21 sec -> choice 25 sec)

V2.0 18/01/2021 – MAJOR RELEASE**New Features:****DMX:**

- Added: control of the size of the DMX packet (sometimes a non-compliant packet passed the UART error tests producing a brief flash)
- Change in the number of DMX slots taken into account (from 7 to 2 start code included)

RDM:

- Added: PID Command_Lock to allow or not different functions in the Control Mode such as:
 - RDM ON/OFF
- Added: PIDs PERFORM_SELFTEST and SELF_TEST_DESCRIPTION to test the device (8 Tests available: Temp Sensors/Power Supply/Fans/Driver/ Signal Leds Red/Signal Leds Green/Signal Leds Blue/ All Tests) a SELFTEST_RESULT Manufacturer PID was created to view the results.
- Added: Manufacturer PID CURRENT_IP_ADDRESS and CURRENT_MASK to easily find the IP address as well as the sub-network mask.
- It is possible to change the serial number via RDM (special procedure) for Service purpose.
- Added a Manufacturer PID CALIBRATION DRIVER PID for driver calibration.
- Added a Manufacturer PID to adjust and display the CUSTOM_RESPONSE_TIME
- Added a Manufacturer PID to address ARTNET and SACN universes
- Added a Manufacturer PID to select the type of Data (DMX/SACN/ARTNET/STANDALONE)
- Added a Manufacturer PID to select the type of DMX_HOLD (HOLD LAST/RESET DMX/STANDALONE)
- Added PIDs for IPV4 E1.37-2 settings.
- Added PID STATUS_MESSAGES
- Added PID MODULATION_FREQUENCY
- Added PID MAXIMUM_LEVEL
- Adding PID DISPLAY_LEVEL

Web Page:

- The possibility of addressing ARTNET and SACN universes

Error Management:

- New PSU error detection management (if an error is detected the projector stays off until the next restart). Changes in error and warning criteria.
- New fan error management (if the speed is less than 80% of the nominal speed or if it drops to 0). Reset the errors if they are temporary. If they last more than 60s the become final until the fixture restarts
- Management of the CPU card Led (at start if OK the Led goes green for 2 minutes then off otherwise the Led goes red and stays always on)
- Checking the format of the serialnumber. In case of error a message is sent by RDM through STATUS_MESSAGES and shown on the display (ARTHUR)

Network:

- Static/dynamic IP management: If switched to DHCP mode, the static IP address (and sub-network mask) is saved and displayed again if returned to static IP.

Corrections/Improvements:

- Calibration optimization (calibration time decreases from 80s to about 10s)
- Change for RDM transport: RDM thru DMX remains functional in DMX, SACN, STANDALONE modes
- EEPROM Restoration Security: In the event of a continuous start loop due to a corruption in the function fixture.workmode, DMX is selected by default.
- DMX_HOLD function
- Output Response Time is on Medium per default value.
- Change the default fixture type 065A instead of 0650 to test per default the local potentiometer version.

RDM:

- Minor changes for displayed text in RDM
- PID Sensors
- Change: Fans description
- Change: Sensor description: ex 48V - PSU instead of 48V - SENSOR
- RDM was not working in Standalone mode.
- Factory Reset now works.

SACN:

- Unable to address a universe beyond 255.
- Possible shutdown if a RDM controller is present on the DMX input.

ARTNET:

- Possible shutdown if a RDM controller is present on the DMX input.
- ARTNET: If ARTNET RDM is on then RDM on DMX line is automatically deactivated (it automatically reactivates if the network is disconnected)
- Affichage version soft dans ARTNET NODE POLL REPLY

Network:

- Restores the stored IP address when switching from an auto IP address without the presence of a DHCP server (IP:0.0.0.0)

Error management:

- Adjusting the minimum speed of the CPU fan to avoid an error.
- The fan operation range has been revised (now takes into account the manufacturer characteristics for max speed and takes into account RJ parameters for min speed depending on the mode of ventilation)
- Solved issue for the Driver 115W Test mode, change driver management to 1 channel mode.
- Change: PSU voltage errors management
 - Error according to min/max threshold (existed before for min but was too low and did not exist for maximum)