



ROBERT JULIAT

BIZET – LEXIE FIRMWARE HISTORY

After updating, refresh your web page and check that you have the following text at the bottom of the page:

ROBERT JULIAT - RJ LED 2 - Version X.XX

It is highly recommended to do a Factory Reset after the update. This can be done from the Web Page or RDM. It should also be noted that user settings will be lost.

V5.01 Build 3662

CRA Compliance

- Secure bootloader - CRP2

Implementation

- Monitoring Software License
- E1.37-4 FTC Protocol (File Upload/Download and Firmware Update)
- Bizet 370M Fresnel

Optimisation/Improvements

- Display
- Fixed self-test mode for production test

V4.05 Build 2512 – Official Release 31/07/24

V4.09 Build 2894 – 17/07/2025

- Improvement: Screen menu
- New function: Home Values
- Optimisation and correction of bugs

RDM

- Improvement: RDM Pid Slot_Info
- Improvement: Status_Messages
- RDM-FTC ready. Firmware update by RDM available but not released officially by ESTA.