



ROBERT JULIAT

BIZET – LEXIE FIRMWARE HISTORY

After updating, refresh your web page and check that you have the following text at the bottom of the page:

ROBERT JULIAT - RJ LED 2 - Version X.XX

It is highly recommended to do a Factory Reset after the update. This can be done from the Web Page or RDM. It should also be noted that user settings will be lost.

V5.02 Build 3676

- Fixed issue after a zoom motor set through DMX it was impossible to control the unit by DMX
- Fixed issue when you select Without PWM impossible to exit from the menu

V5.01 Build 3662

CRA Compliance

- Secure bootloader - CRP2

Implementation

- Monitoring Software License
- E1.37-4 FTC Protocol (File Upload/Download and Firmware Update)
- Bizet 370M Fresnel

Optimisation/Improvements

- Display
- Fixed self-test mode for production test

V4.05 Build 2512 – Official Release 31/07/24

V4.09 Build 2894 – 17/07/2025

- Improvement: Screen menu
- New function: Home Values
- Optimisation and correction of bugs

RDM

- Improvement: RDM Pid Slot_Info
- Improvement: Status_Messages
- RDM-FTC ready. Firmware update by RDM available but not released officially by ESTA.