



ROBERT JULIAT

TRISTAN MORGANE BERLIOZ FIRMWARE HISTORY

After updating, refresh your web page and check that you have the following text at the bottom of the page:

ROBERT JULIAT - RJ LED 2 - Version X.XX

It is highly recommended to do a Factory Reset after the update. This can be done from the Web Page or RDM. It should also be noted that user settings will be lost.

V5.01 Build 3662

CRA Compliance

- Secure bootloader - CRP2

Implementation

- Monitoring Software License
- E1.37-4 FTC Protocol (File Upload/Download and Firmware Update)

Optimisation/Improvement

- Display
- Fixed self-test mode for production test

V4.08 Build 2586 – Official Release 19/12/2024

V4.12 Build 3052 – 19/09/2025

Improvement:

- Screen menu
- Warning messages
- New management for control (potentiometers) and associated functions
- New function: Home Values
- Optimisation and correction of bugs
- Model ID Management

RDM

- Improvement: RDM Pid Slot_Info
- Improvement: Status Messages
- RDM-FTC ready. Firmware update by RDM available but not released officially.