



ROBERT JULIAT

BIZET – LEXIE FIRMWARE HISTORY

After updating, refresh your web page and check that you have the following text at the bottom of the page:

ROBERT JULIAT - RJ LED 2 - Version X.XX

It is highly recommended to do a Factory Reset after the update. This can be done from the Web Page or RDM. It should also be noted that user settings will be lost.

V4.05 Build 2512 – Official Release 31/07/24

V4.09 Build 2894 – 17/07/2025

- Improvement: Screen menu
- New function: Home Values
- Optimisation and correction of bugs

RDM

- Improvement: RDM Pid Slot_Info
- Improvement: Status_Messages
- RDM-FTC ready. Firmware update by RDM available but not released officially by ESTA.